



Brookline
Road Safety Audit
NH 13 / South Main St

Presented to:

Brookline Selectboard

August 23, 2021

Michael Dugas, P.E.
Highway Safety Engineer

https://commons.wikimedia.org/wiki/File:Main_Street,_Brookline_NH.jpg


Agenda

- What is a road safety audit?
- RSA Findings
 - Existing Conditions
 - Safety Concerns
 - Improvement Concepts
 - Next Steps
- Q & A


RSA Definition

*A formal safety performance examination of a location by an independent team. The RSA team is comprised of a **diverse group of stakeholders representing multiple disciplines** and may include local officials such as administration and emergency responders, business and landowners adjacent to the site, etc.*

Brookline RSA - Location




Brookline RSA – Existing Conditions



Brookline RSA – Safety Concerns



RSA – Improvement Concept 1



RSA – Improvement Concept 2



RSA – Improvement Concept 3



RSA – Next Steps

1. Alternatives reviewed with Town
2. Recommendations
 - **Pursue roundabout alternative with federal safety funds**
 - Reduce intersection pavement with 2022 resurfacing project

Questions?

Michael.J.Dugas@dot.nh.gov